

Service Repair Sheet SRS68709

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Swadhipriya Moorthy

Whipps Cross University Hospital

Medical Engineering Department

Clinical Technologist

02085356927

00003450

swadhi.priya@nhs.net

26/Feb/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 21/Feb/2024 Kate Griffiths

21/Feb/2024 Kate Griffiths

Would like to send in MX300s, s/n TEQ171 and TEQ211 for calibration. I cannot find these s/n on i/stats

26/Feb/2024 Robert Connor

Received 2 x MX300i s/n 331064, 340499, with 3 x AA battery, 2 x coiled cable s/n 0010276, 0000303, 2 x base with suction cup feet, spare battery door, spare battery door clip, spare mounting plate, spare keypad, 1 x R17Vi s/n V100046, 1 x R17V s/n V100384.

Ready For quote

CGN007 8.3-24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36279	Oxygen Monitor	0111235	331064	2
SRN36280	Oxygen Monitor	0111237	340499	2
SRN36281	Oxygen Monitor Cable	0131202	0010276	2
SRN36282	Oxygen Monitor Cable	0131202	0000303	2
SRN36283	Oxygen Sensor	0110019	V100046	2
SRN36284	Oxygen Sensor	0110018	V100384	2

0180029 x 2 @ £40 each

S/N's, SRS, SRN → SRN's 36279, 36280.

0131202 x 2 FOC → SRN 36281, 36282.
S/N's SRS, SRN

0140015 x 1 FOC
Old S/N, SRS, SRN → SRN 36283

0110019 x 1 @ £42
New S/N, SRS, SRN

0140015 x 1 FOC
Old S/N, SRS, SRN → SRN 36284

0110018 - x 1 @ £42 - New S/N, SRS, SRN

Add
PPUPS x 1 @ £12



**Whipps Cross
University Hospital**

✓CID2263 Opera 00003450 Type:NHS

Hospital End User

Whipps Cross University Hospital Whipps

Cross Road, Leytonstone, London, , E11

1NR, UK

Tel **02085395522** GBP End User (0001)

Log Call

Add Issue

Credit Credit Credit Limit 0.00GBP

Account Home	Main Details	Account Memos	Sales History	Stock References	Cust./Supp. Returns	Service Visits
Distributor Agreements		Documents Files	Linked Issues	Regulatory Agreements		

Use :0001 GBP End User

Repair SRS68709 Values in Pounds @ £1: £1.00

SRN36279	Oxygen Monitor	0111235			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0180029	1	£40.00	£40.00
SRN36280	Oxygen Monitor	0111237			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0180029	1	£40.00	£40.00
SRN36283	Oxygen Sensor	0110019			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110019	1	£42.00	£42.00
SRN36284	Oxygen Sensor	0110018			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0110018	1	£42.00	£42.00
				Parts Cost	£164.00

**Page updated, TRipple check prices to price
in intrastats main search**

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent



Barts Health
NHS Trust

Medical Engineering Department
Whipps Cross University Hospital

Barts Health NHS Trust
Whipps Cross Road, London
E11 1NR

T: 0208 535 6927
E: swadhi.priya@nhs.net

Viamed Ltd
15 Station Road
Cross Hills
Keighley

West Yorkshire
BD20 7DT

23 February 2024


Dear Service Team,

REF: SRS68709

Please find here with the following equipment:

Line No.	Serial Number	Our Equipment Number	Brand	Model	Description
1	331064	TEQ171	TELEDYNE	MX300	Oxygen Monitor, Galvanic
1	340499	TEQ211	TELEDYNE	MX300	Oxygen Monitor, Galvanic

This equipment is being returned for the following reason:
This test equipment is due for calibration + service

Yours sincerely,

Swadhipriya Moorthy
Clinical Technologist
Barts Health NHS Trust

