

Service Repair Sheet SRS68709

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Swadhipriya Moorthy
Whipps Cross University Hospital
Medical Engineering Department
Clinical Technologist
02085356927

00003450
swadhi.priya@nhs.net

26/Feb/2024
Robert Connor
Viamed
Quote

VIAMEDclean	
Goods In Only Decontamination certificate provided by customer	☒
Cleaned by Viamed, if no decontamination certificate from customer Signed: _____ Date: _____	☐
Goods Out Only Cleaned by Viamed before returning to customer Signed: _____ Date: _____	☐

Notes 21/Feb/2024 Kate Griffiths

21/Feb/2024 Kate Griffiths

Would like to send in MX300s, s/n TEQ171 and TEQ211 for calibration. I cannot find these s/n on i/stats

26/Feb/2024 Robert Connor

Received 2 x MX300i s/n 331064, 340499, with 3 x AA battery, 2 x coiled cable s/n 0010276, 0000303, 2 x base with suction cup feet, spare battery door, spare battery door clip, spare mounting plate, spare keypad, 1 x R17Vi s/n V100046, 1 x R17V s/n V100384.

Ready For quote

CCNEN 8.3-24

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36279	Oxygen Monitor	0111235	331064	2
SRN36280	Oxygen Monitor	0111237	340499	2
SRN36281	Oxygen Monitor Cable	0131202	0010276	2
SRN36282	Oxygen Monitor Cable	0131202	0000303	2
SRN36283	Oxygen Sensor	0110019	V100046	2
SRN36284	Oxygen Sensor	0110018	V100384	2

0180029 x 2 @ £40 each

S/N's SRS, SRN → SRN's 36279, 36280.

0131202 x 2 FOC

S/N's SRS, SRN → SRN 36281, 36282.

- NO fault found.

0140015 x 1 FOC

Old S/N, SRS, SRN → SRN 36283

0110019 x 1 @ £42

new S/N, SRS, SRN

0140015 x 1 FOC

Old S/N, SRS, SRN → SRN 36284

0110018 - x 1 @ £42 - new S/N, SRS, SRN

Add
PPUPS x 1 @ £12