


CS Full, MG Full



Brian Goldthorpe

 CID27158 Opera CID27158 Type:Vandagraph Retail
Brian Goldthorpe 9 Green Hill Drive , , Leeds , , LS13 4JZ, United Kingdom
 Tel **01132638897** GBP Retail Price List Vandagraph (0010) 

Add Issue

Proforma Credit Limit 0.00GBP



 Account Home

 Main Details

Account Memos

Sales History

Stock References

⦿ Cust./Supp. Returns

 Service
Visits

Distributor Agreements

Documents
Files

 **Linked
Issues**

Regulatory Agreements

SRS68692

SRS Created : 07 Feb 2024

Created By Ryan Swaine
On Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

Upload Document to SRS

ADD DOCUMENT TO SRS :	Document Description
-----------------------------	-------------------------

Next

Choose a file to upload: No file chosen

Choose file

No file chosen

Handle with care

Add Items to Supplier Returns Box

Add

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68692		Notes
SELECT * FROM viamedquoteaddress where ID='27158'		07/Feb/2024 Ryan Swaine
Company / Hospital	Brian Goldthorpe	07/Feb/2024 Ryan Swaine
Contact Name	Brian Goldthorpe	Purchased a R-33DE for his analox analyser and it did not work, we have since replaced it, but it still does not work. Looks like it could be the analyser. He is going to send the whole lot for us to evaluate.
Department		07/Feb/2024 Ryan Swaine
Position		Please give them to MG upon receipt.
Company Phone	01132638897	15/Feb/2024 Robert Connor
Direct Phone	01132638897	Received 1 x analox, with R-33DE s/n 930359
Opera Account	CID27158	04/Mar/2024 Catherine Spence
Email	brian@bgoldthorpe.me.uk	in engineers room
Order Number		
Viamed ORD Number		
Date Received Into building	15 Feb 2024	
Type	Quote Before Repair Move to Repair	
Issues?	323107	

Items for Repair

... ..

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36268	Oxygen Analyser	Requires Service Manual Linking in System		12134	Analox	No	No	Complete - Repaired 08 Mar 2024 Michael Green	No Reading	01:00
SRN36268 Engineer Notes: INTERNAL NOTES not for customer discussion 08/Mar/2024 Michael Green The Analox analyser has been repaired. The sensor cable has been replaced.										
SRN36269	Oxygen Sensor Vandagraph	0110224 Requires Service Manual Linking in System	 2333527	930359		Yes	No	No Fault Found 08 Mar 2024 Michael Green	No Fault Found	00:00
SRN36269 Engineer Notes: INTERNAL NOTES not for customer discussion 08/Mar/2024 Michael Green The R-33DE Oxygen sensor has been tested. No fault was found.										

Currently Viewing ITEM SRN36268 Oxygen Sensor Vandagraph 0110224 930359

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The R-33DE Oxygen sensor has been tested. No fault was found.	08/Mar/2024 Michael Green The R-33DE Oxygen sensor has been tested. No fault was found.	The R-33DE Oxygen sensor has been tested. No fault was found.

-

ISO REVIEW
Instructions

Please Select