

Service Repair Sheet SRS68710

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Dan Jones

Glangwili General Hospital

Clinical Engineering Department

Specialist Clinical Technologist

01267227793

01267 235151

00000088

dan.jones@wales.nhs.uk

11/Mar/2024

Robert Connor

Viamed

Warranty

**VIAMEDclean**

**Goods In Only**

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

**Goods Out Only**

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 21/Feb/2024 Steve Hardaker

21/Feb/2024 Steve Hardaker

Returning a Max-550E sensor not calibrating in a MaxBlend Lite blender. When calibrated at 100%, it won't drop down to less than 24%.

S/n JF95399089, sold 8/2/24.

11/Mar/2024 Robert Connor

Received 1 x MAX550E s/n JF95399089

Ready For quote

Repair Complete Signed

Canen 13.3.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36306	Oxygen Sensor	0110452	JF95399089	Yes

0140013 x 1 FOC  
Old S/N, SRS, SRN

0110452 x 1 FOC  
New S/N, SRS, SRN

UPS x 1 FOC



# VIAMED

Viamed Limited · 15 Station Road · Cross Hills  
Keighley · West Yorkshire · BD20 7DT · United Kingdom  
Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582  
Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68710

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Dan Jones

Glangwili General Hospital

Clinical Engineering Department

Specialist Clinical Technologist

01267227793

01267 235151

00000088

dan.jones@wales.nhs.uk

11/Mar/2024

Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36306	0110452	JF95399089	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110452

Replaced under warranty with S/N JF95399099

---



# CLINICAL ENGINEERING DEPARTMENT



Bwrdd Iechyd Prifysgol  
Hywel Dda  
University Health Board

	ITEM A	ITEM B	ITEM C	ITEM D
EQUIPMENT TYPE	Oxygen Sensor			
INV No	87996117			
SERIAL No	JF95399089			
MAKE	MAXTEC			
MODEL	MAX-550E			
JOB NUMBER	N/A			
COMPANY REF/RMA	SRS68710			

## DECLARATION OF DECONTAMINATION

DATE 22/02/2024

+ What method of decontamination has been used? Please provide details.

Has the item(s) been Decontaminated? Yes <sup>†</sup> No <sup>‡</sup>	Cleaning N/A NEW
† Explain why the item has not been decontaminated?	Disinfection
	Sterilization

**FAULT DESCRIPTION:** Reading will not read lower than 23.8%. Calibrating at 100% o.k. However, with oxygen removed and air flow at 4lpm still indicated 23.8%

**Contact Name:** Dan Jones

**Email:** dan.jones@wales.nhs.uk

**Telephone:** 01267-227793

**NOTE:** PLEASE ENCLOSE SERVICE REPORT WITH RETURNING UNIT

Date: 30.11.20  
Doc. Ref: F001 Medical Equipment Dispatch Form

Rev003

Page 1 of 2