

Service Repair Sheet SRS68656

Contact Name

Marie Birgersson

Company/ Hospital Name

Swevet - AB

Department

Position

Direct Phone

46771215500

General Phone

46771215500

Opera Account

00006308

Email

marie.birgersson@swevet.se

Order Number

Date Received

04/Jan/2024

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC

Date: 4/1/24

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes Faulty 0012165. It says

28/Dec/2023 Kate Griffiths

S/N is T2201110022 - in warranty, purchased November 2023

04/Jan/2024 Robert Connor

Received 1 x VM-2176 s/n T2201110022, with hard plastic carry case, CD, lanyard, silicone cover, Y probe s/n VYV210035, small clip and large clip.

Ready For quote

Repair Complete Signed

CC Connor 15.3.24

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|-------------------------|-----------|---------------|----------|
| SRN36207 | Pulse Oximeter | 0012176 | T2201110022 | Yes |
| SRN36208 | Pulse Oximetry Y Sensor | 0015002 | VYV210035 | Yes |

0042160 x 1 FOC
S/N, SRS, SRN

0040001 x 1 FOC
S/N, SRS, SRN

UPS 24x15x15cm 0.50kg FOC.

Service Repair Sheet 68656

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Marie Birgersson

Swevet - AB

46771215500

46771215500

00006308

marie.birgersson@swevet.se

04/Jan/2024

Robert Connor

| Repair | Ref | S/N | Equipment Type | Under Warranty |
|----------|---------|-------------|----------------|--|
| SRN36207 | 0012176 | T2201110022 | Pulse Oximeter | Complete - Repaired Time :0 Hour(s) |

The VM2160 Vet pulse oximeter has been repaired under warranty. The SpO2 module has been replaced.

| Repair | Ref | S/N | Equipment Type | Under Warranty |
|----------|---------|-----------|-------------------------|-----------------------------------|
| SRN36208 | 0015002 | VYV210035 | Pulse Oximetry Y Sensor | No Fault Found Time :0 Hour(s) |

The SpO2 Y sensor has been tested. No fault was found.



Proforma invoice No F8021

Ship to: Date 2023-12-28

Returns Dept- SRS68656

Viamed Ltd
15 Station Road
Cross Hill Keighley
BD20 7DT West Yorkshire UK
Contact : Kate Griffiths

<http://www.viamed.co.uk>

Email: kate.griffiths@viamed.co.uk

Tel: +44 (0)1535 634542

Fax: +44 (0)1535 635582

Shippers name:

Swevet AB
Forskaregatan 1D

SE-275 37 SJÖBO

Contact: Magnus Persson

Mail: magnus.persson@swevet.se

This is veterinary equipment for repair, Equipment will return.

| Nr | Description |
|---------|--|
| 4410540 | Viamed SpO2 VM-2160 + sensor VY6500VM and box 1 Pc |

S/n: T2201110022

Value : 245 EUR

Ref. SRS68656

Magnus Persson

2023-12-28

Tel +46 416-25821

Orgnr 556621-5843

VAT SE556621584301

Country of manufacture: GB

Weight: 1kg

Measure: 200x250x220mm

Tariffnr : 90189084

VAT Reg No: GB287389593

Eori No: GB287389593000