

Service Repair Sheet SRS68714
Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Miroslav Trebicky
ATAL s.r.o.
Quality Manager
420381251791
00006059
trebicky@actia.cz
07/Mar/2024
Robert Connor
Viamed
Warranty

VIAMEDclean	
Goods In Only Decontamination certificate provided by customer	☐
Cleaned by Viamed if no decontamination from customer	☐
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 26/Feb/2024 Kate Griffiths
26/Feb/2024 Kate Griffiths
will send back three faulty sensors: s/n 984857, 969786 and 970696 under warranty
06/Mar/2024 Kate Griffiths
tracking Fedex 775430219760
06/Mar/2024 Kate Griffiths
due here 7.3.24 before 18.00
07/Mar/2024 Kate Griffiths
delayed, due Friday
07/Mar/2024 Robert Connor
Received 3 x R22A s/n 969786, 970696, 984857.

Ready For quote

Repair Complete Signed

19
C. Green 15.3.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36303	Oxygen Sensor	0110122	969786	Yes
SRN36304	Oxygen Sensor	0110122	970696	Yes
SRN36305	Oxygen Sensor	0110122	984857	Yes

old 0140013 x 3 FOC
S/N's, SRS, SRN's

0110122 x 3 FOC
New S/N's, SRS, SRN's

UPS x 1 FOC

PROFORMA INVOICE No.:740014

Supplier: ATAL s.r.o.

Order No. :

Lesní 47, Horký
390 01 Tábor

ID : 47216719

VAT ID : CZ47216719

ATAL s.r.o. je zapsána v obchodním rejstříku vedeném Krajským soudem v Českých
Budějovicích, oddíl C, vložka 1822.

Deliver to : Viamed Ltd - Returns Department

15 Station Road
BD20 7D West Yorkshire

Customer : VIAMED LTD

15 Station Road
BD20 7D West Yorkshire
GB
ENGLAND

ID :

VAT ID :

ID :

VAT ID :

Due Date : 20.3.2024

Issue Date : 6.3.2024

Payment Condition : DON'T PAY

Delivery description : RECLAMATION

Delivery condition :

Our Order No. :

Item No.	Article	Quantity	Description Unit	Unit Price	Price	Disc. %	+/- %	Total Price
1	PTI 0AS00915		Oxygen sensor R-22A 969786, 984857					
		2,00	ks	27,80	55,60	0,00		55,60
2	PTI 0AS00915		Oxygen sensor R-22A 970696					
		1,00	ks	27,80	27,80	0,00		27,80
		3,00			83,40			83,40

Invoice total USD

83,40

RMA: SRS68714

Taric: 9027 10 90

NOT FOR SALE
CUSTOMS VALUE ONLY

Incoterms:DAP

Tel: +420 381 410124

E-mail: info@atal.cz

ČSOB a.s., Radlická 333/150, Praha 5, č.ú.: 512501423/0300(CZK)

Swift code: CEKOCZPP, IBAN: CZ13 0300 0000 0002 7230 4753(USD)

ČSOB a.s., Radlická 333/150, Praha 5, č.ú.: 272305203/0300(EUR)



VIAMED

Viamed Limited · 15 Station Road · Cross Hills
Keighley · West Yorkshire · BD20 7DT · United Kingdom
Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582
Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68714

Contact Name

Company/ Hospital Name

Position

General Phone

Opera Account

Email

Date Received

Booked in By

Miroslav Trebicky

ATAL s.r.o.

Quality Manager

420381251791

00006059

trebicky@actia.cz

07/Mar/2024

Robert Connor

Repair Ref S/N
SRN36303 0110122 969786

Equipment Type
Oxygen Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110122

Replaced under warranty with S/N 994236

Repair Ref S/N
SRN36304 0110122 970696

Equipment Type
Oxygen Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110122

Replaced under warranty with S/N 994237.

Repair Ref S/N
SRN36305 0110122 984857

Equipment Type
Oxygen Sensor

Under Warranty

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110122

Replaced under warranty with S/N 994238.