Service Repair Sheet SRS68702 Contact Name Company/ Hospital Name Department Position Direct Phone General Phone Opera Account Email Order Number

Date Received Booked in By Main Company Type Return

Shelly Dean Pullman Instruments (UK) Ltd

01423720360 01423720360 00011971 purchasing@pullman.co.uk 19/Feb/2024

Catherine Spence Viamed Quote

VIAMEDCIE Goods In Only Decontamination certificate provided by customer	an $\Box$
Cleaned by Viamed, if no declaration certificate from customer Signed:	
Goods Out Only Cleaned by Viamed b returning to customer Signed: Date:	efore

Notes 19/Feb/2024 Catherine Spence

VG900 for testing and calibration. Received from pullman Instruments but label on unit is for Newcastle upon tyne hospital asset id 124268

Unit has a modified nellcor adapter

Looks like the unit has a calibration label on it from 31/01/2024.

Serial Number of Unit CK62504947 supplied with batteries, To be tested as we are unable to calibrate it

04/Mar/2024 Catherine Spence

in engineers room processing certificate

07/Mar/2024 Catherine Spence

With Steve Nixon arranging a part number and cost for this repair

07/Mar/2024 Catherine Spence

With Steve Nixon arranging a part number and cost for this repair

15/Mar/2024 Catherine Spence

Received the part number off Steve Nixon for a functional test. p/N 0083100

15/Mar/2024 Catherine Spence

Duplicated SRS for this repair also on SRS68695, copied and pasted notes from that repair: 12/Feb/2024 Steve Hardaker Sending a VG900 for a service check. Doesn t know the serial number.

We advised 1/2h labour unless repairs are needed.

We have already been provided with a PO but at zero value, so please state their PO number 57147 on the quote and asked for it to be updated

15/Mar/2024 Catherine Spence

Please note the zero value Po that was sent in is 257147 and not 57147

Ready For quote

GNEEN 15:3:24

Repair Complete Signed

-GREON 21.3.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36273	Pulse Oximeter Tester	0013100	CK62504947	7

0083100 × \$0 290 a 290 charge for 1/2hr = 245 SIN, SPS, SEN Add line as Exw-collect in Person.



VIAMED

15 STATION ROAD

CROSS HILLS

KEIGHLEY

WEST YORKSHIRE

BD20 7DT

## Product Code Product Description CAL PLEASE CALIBRATE INST SP02 SENSOR TEST UNIT VG900 MISC ID 124268 JN 510032-17

## **Purchase Order**

Order no 257147

Account ref VIA001

Date 06/02/2024

Pullman Instruments Harrogate
E:purchasing@pullman.co.uk
for any enquiries or to arrange collections

Qty Ordered	Unit D Price	% rate	Price
0.00	0.00		0.00
1.00	45.00	0.00	45.00
0.00	0.00		0.00

Pullman Instruments (UK) Ltd

E: sales@pullman.co.uk Ltd

www.pullman.co.uk

3 Greengate, Cardale Park

Company Reg No 3681420

Registered address at

Harrogate, HG3 1GY

VAT Reg 545 674 908

**ESG House** 

Harrogate

HG1 5HX

Chatsworth Road

North Yorkshire

T: 01423 720360 F: 01423 720361

PLEASE ACKNOWLEDGE RECEIPT OF THIS ORDER AND PROVIDE A DATE FOR RETURN DELIVERY / COLLECTION

Any additional costs must be agreed before proceeding

Total Net 45.00
Carriage 0.00
Total Tax 9.00
Order Total 54.00

## Delivery address (if other than the address above):

## For Pullman use only

Item no.	Date Recd Delivery Note No.		Goods checked	
	WENT E			

Form F05 Issue 27 Date: 28 Aug 19 Approved by:

Regional Offices & Laboratories

- Pullman Instruments Central Milton Keynes 01908 568250
- Pullman Instruments North West
   Wigan 01942 526164
- Pullman Instruments South West
   Weston Super Mare 01934 424575



Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68702

Contact Name

Company/ Hospital Name

Direct Phone General Phone Opera Account

Email

Order Number Date Received Booked in By

Shelly Dean

Pullman Instruments (UK) Ltd

01423720360 01423720360 00011971

purchasing@pullman.co.uk

257147 19/Feb/2024 Catherine Spence

Repair SRN36273 Ref

S/N 0013100 CK62504947 **Equipment Type** 

Pulse Oximeter Tester

Calibrated

Time: 0.5 Hour(s)

Parts Replaced

0083100 Qty: 0.5

The VG900 test unit has been tested. The unit is working as expected.