

Service Repair Sheet SRS68709
 Contact Name
 Company/ Hospital Name
 Department
 Position
 Direct Phone
 General Phone
 Opera Account
 Email
 Order Number
 Date Received
 Booked in By
 Main Company
 Type Return

Swadhipriya Moorthy
 Whipps Cross University Hospital
 Medical Engineering Department
 Clinical Technologist
 02085356927

00003450
 swadhi.priya@nhs.net

26/Feb/2024
 Robert Connor
 Viamed
 Quote

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	<input checked="" type="checkbox"/>
Cleaned by Viamed, if no declaration certificate from customer	<input type="checkbox"/>
Signed: _____	
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 21/Feb/2024 Kate Griffiths

21/Feb/2024 Kate Griffiths

Would like to send in MX300s, s/n TEQ171 and TEQ211 for calibration. I cannot find these s/n on i/stats

26/Feb/2024 Robert Connor

Received 2 x MX300i s/n 331064, 340499, with 3 x AA battery, 2 x coiled cable s/n 0010276, 0000303, 2 x base with suction cup feet, spare battery door, spare battery door clip, spare mounting plate, spare keypad, 1 x R17Vi s/n V100046, 1 x R17V s/n V100384.

Ready For quote

CGNEON 8.3-24

Repair Complete Signed

CGNEON 8.21.3.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36279	Oxygen Monitor	0111235	331064	2
SRN36280	Oxygen Monitor	0111237	340499	2
SRN36281	Oxygen Monitor Cable	0131202	0010276	2
SRN36282	Oxygen Monitor Cable	0131202	0000303	2
SRN36283	Oxygen Sensor	0110019	V100046	2
SRN36284	Oxygen Sensor	0110018	V100384	2

0180029 x 2 @ £40 each

S/N's, SRS, SRN → SRN's 36279, 36280.

0131202 x 2 FOC

S/N's SRS, SRN → SRN 36281, 36282.
 - NO fault found.

0140015 x 1 FOC

Old S/N, SRS, SRN → SRN 36283

0110019 x 1 @ £42

New S/N, SRS, SRN

★ Add New S/N

0140015 x 1 FOC

Old S/N, SRS, SRN → SRN 36284

0110018 - x 1 @ £42 - New S/N

Add
 PPUPS x 1 @ £12

SRN's, SRS, SRN ★ Add New S/N