Service Repair Sheet SRS68645

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Morne Leukes

SSEM Mthembu Medical (Pty) Ltd

000114307000

CID11237 mornel@ssemmthembu.co.za

21/Mar/2024

Robert Connor

Viamed

Quote

	VIAMEDCLEAN Goods In Only Decontamination certificate provided by customer	
1	Cleaned by Viamed, if no declaration certificate from customer RS Signed: 21/3/24	
-	Goods Out Only Cleaned by Viamed before returning to customer	

Notes 04/Dec/2023 Kate Griffiths

04/Dec/2023 Kate Griffiths

Would like to send in 6 x V1000 for calibration. s/n: PR02810A10-15

Received 5 x V1000 s/n PR02810A11, PR02810A12, PR02810A13, PR02810A14, PR02810A15.

Ready For quote

Careen 3.424

Repair Complete Signed

CDN	Equipment	Stock Ref	Serial Number	Warranty
SRN	Foetal Simulator	1410000	PR02810A11	12
SRN36326 SRN36327	Foetal Simulator	1410000	PR02810A12	2
SRN36328	Foetal Simulator	1410000	PR02810A13	2
SRN36329	Foetal Simulator	1410000	PR02810A14	1
SRN36330	Foetal Simulator	1410000	PR02810A15	2

Proforma

1480000 x 5 @ SIN'S SRS, SRN'S

1430309 x 5 SPS, SEN'S.

BC? 105.

UPS X 1

5kg 31x31x25cm.