



Service Repair Sheet 68744

Contact Name

Company/ Hospital Name

Department Position

General Phone Opera Account

Email

**Date Received** Booked in By

Derek Smith

Vet Direct Services Ltd Repairs Department

**Technical Support Co-Ordinator** 

0191 2642705 00012824

derek.smith@vet-direct.com

03/Apr/2024 Robert Connor

Repair SRN36351 0111275 A106341

Ref

S/N

**Equipment Type** Oxygen Analyser Under Warran

Complete - Repaired Time: 0 Hour(s)

The unit was making a very poor contact on the battery. After adjusting the battery position everything worked as expected.

Repair SRN36352 Ref

S/N 0110660 A111130

**Equipment Type** Oxygen Sensor

Under Warra

No Fault Found Time: 0 Hour(s)

No fault found with the sensor.