

Service Repair Sheet SRS68746

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mr Mahesha

BDI India Private Limited

Customer Support

Customer Support

918022560418

918022560418

00006454

mahesha@bdi-india.com

08/Apr/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐Cleaned by Viamed,
if no declaration certificate
from customer ☒Signed: RCDate: 8/4/24

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 02/Apr/2024 Kate Griffiths

02/Apr/2024 Kate Griffiths

Calibration of 5 V1000s: S/N: PR02380A14, PR02529A10, PR02529A12, PR02540A12, PR02529A24. Have asked that they be sent in clean and for a decont. cert.

03/Apr/2024 Kate Griffiths

DHL track. no. 6222881965 Due here 8th Apr.

08/Apr/2024 Robert Connor

Received 5 x V1000 s/n PR02380A14, PR02529A10, PR02529A12, PR02529A24, PR02540A12. Units have not been cleaned since last being seen, and surface cleanse with clinell wipes was not sufficient, units require deep clean before repair.

Ready For quote

CGreen 10.4.24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36357	Foetal Simulator	1410000	PR02380A14	2
SRN36358	Foetal Simulator	1410000	PR02529A10	2
SRN36359	Foetal Simulator	1410000	PR02529A12	2
SRN36360	Foetal Simulator	1410000	PR02529A24	2
SRN36361	Foetal Simulator	1410000	PR02540A12	2

1480000 x 5 @ \$63.40

S/N's, SRS, SRN's

1430309 x 5 @ FOC

SRS, SRN's

1440001 -> CG 16.4.24

1440000 x 1 @ \$66.

See skype message for wording.

ups x 1 ^{31x31x25cm} 4kg.