

Viamed Limited - 15 Station Road - Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 Fax: +44 (0)1535 635 582 Email: Info@vlamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68767

Contact Name

Company/ Hospital Name

Position

Direct Phone General Phone Opera Account

Email

Date Received Booked in By

Claire Snaith

Vet Direct Services Ltd **Technical Support Nurse** 

08000683300 01912642705 00012824

tech@vet-direct.com

02/May/2024 Robert Connor

Repair

Ref

S/N SRN36405 0111275 A106087 Equipment Type Oxygen Analyser

**Under Warranty** 

Complete - Repaired Time: 0 Hour(s)

Analyser was reading low.

I have adjusted the output to correct it.

Repair

Ref

S/N SRN36406 0110660 A111112 Equipment Type Oxygen Sensor

**Under Warranty** 

No Fault Found Time: 0 Hour(s)

No fault found.