

Service Repair Sheet SRS68767

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Claire Snaith

Vet Direct Services Ltd

Technical Support Nurse

08000683300

01912642705

00012824

tech@vet-direct.com

02/May/2024

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC
Date: 2/5/24

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 26/Apr/2024 Steve Hardaker

26/Apr/2024 Steve Hardaker

Returning a MySign O, serial number A106087 under warranty. Fault not specified.

This was purchased Feb 23 with sensor serial number A110786

They bought a new sensor, s/n A111112 on 27/3/24 but it didn't fix the problem. They might return it with this one, or the original sensor that was supplied with the device (s/n A110786), or both.

Please let me know what you find.

02/May/2024 Robert Connor

Received 1 x OxiQuant S s/n A106087, with OOI103 s/n A111112, flow diverter, oxygen stem, and blue tee.

Ready For quote

Repair Complete Signed

CGreen 8-5-24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36405	Oxygen Analyser	0111275	A106087	Yes
SRN36406	Oxygen Sensor	0110660	A111112	Yes

} part of
same
unit.
cg 8-5-24

0140137 x 1 FOC.

Includes sensor (s/n A111112, SRS 68767, SRN 36406)

~~SRS 68~~
SRS number, SRN number.

BPS x 1 FOC.