



Internal job reference: CWKD0763728

PO number if applicable:

RMA: SR568763

Date: 24/04/2024

Asset/Equipment/Serial Number: Asset: 314944 SN: 312948

Viamed Ltd

To whom it may concern

Please find enclosed MX300 Oxygen Monitor. Unit unable to complete calibration, device showing sensor error on screen, batteries have been replaced and sensor is new. In need for repair.

Please return to
Siemens Workshop (Level 0)
Worcestershire Royal Hospital
Charles Hastings Way
Worcester
WR5 1DD

Please send all quotations to worcester.team@siemens-healthineers.com or Tel: 01905 733176

Yours sincerely

Shon Puthusseriyil

Return Address:

Siemens Healthineers Ltd

Loading Bay, Worcestershire Royal Hospital,

Charles Hastings Way, Worcester WR5 1DD

Tel : 01905 733026 / 01905 733176

Email worcester.team@siemens-healthineers.com