

Viamed Limited - 15 Station Road - Cross Hills Keighley - West Yorkshire - BD20 7DT - United Kingdom Tel: +44 (0)1535 634 542 - Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68764

Contact Name

Company/ Hospital Name

Position

Direct Phone

General Phone Opera Account

Email

Date Received

Booked in By

Claire Snaith

Vet Direct Services Ltd

Technical Support Nurse

08000683300 01912642705

00012824

tech@vet-direct.com

07/May/2024

Robert Connor

Repair Ref SRN36413 0111275 A106115

S/N

Equipment Type Oxygen Analyser **Under Warranty**

Complete - Repaired

Time: 0 Hour(s)

Analyser was reading low.

I have adjusted the output to correct it.

Repair

Ref S/N

SRN36414 0110660 A110814

Equipment Type Oxygen Sensor

No Fault Found Time: 0 Hour(s)

The sensor is no fault found.