

Service Repair Sheet SRS68764

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Cobra Account

Email

Order Number

Date Received

Checked in By

Main Company

Time Return

Claire Snaith

Vet Direct Services Ltd

Technical Support Nurse

08000683300

01912642705

00012824

tech@vet-direct.com

07/May/2024

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes: 26/Apr/2024 Steve Hardaker

26/Apr/2024 Steve Hardaker

Received 1 x OxiQuant S s/n A106115, customer reporting as faulty (unspecified) even when a new sensor was tried. Under warranty.

07/May/2024 Robert Connor

Received 1 x OxiQuant S s/n A106115, with OOI103 s/n A110814, flow diverter, blue tee, and oxygen stem.

Sensor battery replaced by customer.

Ready For quote

Repair Complete Signed

CGreen 13.5.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36413	Oxygen Analyser	0111275	A106115	Yes
SRN36414	Oxygen Sensor	0110660	A110814	void

Part of same unit

0140137

S/N, SRS, SRN

Also include S/N, SRS, SRN of sensor.

UPS

UPS + 1 £0. FOC