

Service Repair Sheet 68749

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone

Opera Account Email

Order Number Date Received

Booked in By

David Blackwell

Darent Valley Hospital Surgical Services Division

Anaesthetic Practitioner Manager

01691 404306 01322 42 81 00 00001365

david.blackwell@dvh.nhs.uk

300089763 24/Apr/2024 Robert Connor

Ref Repair

S/N SRN36385 1410000 PR02643A13 **Equipment Type**

Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 1430309 1480000 Qty: 1

V1000 has had transducer interface cushion replaced and calibration has been checked.