

Viamed Limited 15 Station Road Keighley - West Yorkshire - BD20 7DT - United Kingdom Tel: +44 (0)1535 634 542 - Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68773

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone General Phone Opera Account

Email

Date Received Booked in By

Jaspal Saimbi

Worthing Hospital Medical Electronics

EBME Specialist Technician

01903 205111 01903205111

00012604

jaspal.saimbi@nhs.net

09/May/2024 Robert Connor

Repair SRN36415 1410000 PR0773A29

Ref

S/N

Equipment Type

Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

1480000 Qty: 1 Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.