



Kristian Saksida

 CID28705 Opera CID28705 Type:Vandagraph Retail

Kristian Saksida 130 Harts Creek Lane , Northwood , Christchurch , , CAN 8051,
New Zealand

Tel **+64275558332** GBP Retail Price List Vandagraph (0010)

 Log Call

Add Issue

Proforma Credit Limit 0.00GBP

Account

 [Main](#)

Account Memos

 Sales

 Stock

🔄 Cust./Supp. Returns

 Service

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS68774

SRS Created : 07 May 2024

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)

[Print A4 Sheet](#)

Split Items into Different SRS Numbers

[Edit Details](#)

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Service Repair Sheet 68774		Notes									
Company / Hospital	Kristian Saksida	07/May/2024 Ryan Swaine									
Contact Name	Kristian Saksida	07/May/2024 Ryan Swaine									
Department		Returning R-33DE that was purchased online (VANWEB2139). Customer requires the R-22AT, to send as soon as the R-33DE arrives.									
Position											
Company Phone	+64275558332	Please let RS know when it arrives.									
Direct Phone	+64275558332	22/May/2024 Robert Connor									
Opera Account	CID28705	Received 1 x R33DE s/n 121892									
Email	kris@saksida.com										
Order Number											
Viamed ORD Number											
Date Received Into building	22 May 2024										
Issues?											
Items for Repair											
...											
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)	

22/05/2024, 15:06

SRS View

SRN36462	Oxygen Sensor Vandagraph	0110224 Requires Service Manual Linking in System	 2413850	121892		Yes	No	Unchecked - Returned to Stock		00:00
--------------------------	--------------------------	---	---	--------	--	-----	----	-------------------------------	--	-------

Currently Viewing ITEM SRN36462 Oxygen Sensor Vandagraph 0110224 121892

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

ISO REVIEW
Instructions

Please Select