Service Repair Sheet 68689

Contact Name

Company/ Hospital Name

Direct Phone General Phone Opera Account

Email

Order Number Date Received Booked in By

Damion Walters

Huntleigh Healthcare Ltd

02920 485885 02920485885 00011875

damion.walters@arjo.com

paid via Square 16/May/2024 Robert Connor

Repair SRN36450 1410000 PR02467A11

Ref

S/N

Equipment Type

Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 Qty: 1

1480000 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.