Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68776

Contact Name

Company/ Hospital Name

Department Position

General Phone Opera Account

Email

Order Number Date Received Booked in By Mojisola Idowu

Whittington Hospital Medical Physics

Clinical Engineer 0207 272 30 70

00003460

mojisola.idowu2@nhs.net

WHH544953 13/May/2024 Robert Connor

Repair SRN36416 Ref

S/N

Equipment Type

1410000 GA71182667

Foetal Simulator

Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1

1430309

Qty: 1

1480000

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair

Ref

S/N

Equipment Type

SRN36417 1410000 GE71743919

Foetal Simulator

Complete - Repaired

Time: 0 Hour(s)

Parts Replaced

Qty: 1

1480000

Qty: 1

1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.