



Rex Bisson

CID28973 Opera CID28973 Type:Vandagraph Retail

Rex Bisson Bon Air, Houmet Lane, Vale, , GY6 8JG, Guernsey

Tel 07781120308 GBP Retail Price List Vandagraph (0010) Log Call Add Issue

Proforma Credit Limit 0.00GBP

Account Home

Main Details

Account Memos

Sales History

Stock References

Cust./Supp. Returns

Service Visits

Distributor Agreements

Documents Files

Linked Issues

Regulatory Agreements

SRS68780

SRS Created : 14 May 2024
Created By Ryan Swaine
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System. - will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68780										Notes 14/May/2024 Ryan Swaine 14/May/2024 Ryan Swaine TEK-OX sn. 0542 Test and quote for repair. Please give to MG upon receipt. 28/May/2024 Robert Connor Received 1 x Tek-ox s/n TX0542, in hard yellow case with blue tee.												
Company / Hospital	Rex Bisson																					
Contact Name	Rex Bisson																					
Department																						
Position																						
Company Phone	07781120308																					
Direct Phone	07781120308																					
Opera Account	CID28973																					
Email	kangaroo@cwgsy.net																					
Order Number																						
Viamed ORD Number																						
Date Received Into building	28 May 2024																					
Type	Quote Before Repair Move to Repair																					
Issues?																						
Items for Repair																						
...																						
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)												
SRN36466	Oxygen Analyser	9710203 Requires		0542	Oxygen Analyser	No	No	Unfinished		00:00												

https://vmserver10.thevault.me.uk/intranet/databases/repairs/viewrepair2.php?zz=1&vui=13&user=Ryan Swaine&idp=raxYXanx9ACow&submen...

1/2

30/05/2024, 15:55

SRS View

TEK-OX	Service Manual Linking in System	TEK-OX							
SRN36466 Engineer Notes: INTERNAL NOTES not for customer discussion 30/May/2024 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. The corrosion has spread to the wiring loom. The PCB does power up, but gives a false reading without a sensor connected.									

Currently Viewing ITEM SRN36466 Oxygen Analyser TEK-OX 9710203 0542 Oxygen Analyser TEK-OX

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	30/May/2024 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. The corrosion has spread to the wiring loom. The PCB does power up, but gives a false reading without a sensor connected.	Non added Yet

ISO REVIEW

Please Select

Instructions