

Service Repair Sheet SRS68778

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Sudath Weeraman
Prime Lanka Associate

9410718732285

00006714
sudathweeraman17@gmail.com

04/Jun/2024
Robert Connor
Viamed
Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer

☐

Cleaned by Viamed
if no declaration certificate
from customer

☐

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 10/May/2024 Janine Gill

10/May/2024 Janine Gill

S/N: JC88599026 - Problem - indicates oxygen percentage is too high.

Sent SRS number with instruction on where to send back

04/Jun/2024 Robert Connor

Received 1 x R22MEDV s/n V119584, 1 x MAX-250E s/n JC88599026. Parcel tampered with by DHL.

Ready For quote

Repair Complete Signed

CAneen 11.6.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36476	Oxygen Sensor	0110429	JC88599026	Yes

Customer repair work with SRS 68762
RC 4/6/24

0140013 x 1 FOC
old S/N, SRS, SRN

0110429 x 1 FOC
New S/N, SRS, SRN

UPS FOC

Also to be shipped with SRS 68762.

or EXW if wanting to ship with
next order.