

Service Repair Sheet 68807

Contact Name

Company/ Hospital Name

Position

Direct Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Derya Delmont

Queens Hospital/Siemens Medical Solutions

Technical Administrator

01708 435482

00000264

derya.delmont.ext@siemens-healthineers.com

4515261994

10/Jun/2024

Robert Connor

Repair	Ref	S/N	Equipment Type
SRN36492	1410000	PR02912A12	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
