Service Repair Sheet 68806

Contact Name

Company/ Hospital Name

Direct Phone General Phone Opera Account

Email

Order Number

Date Received Booked in By

Damion Walters

Huntleigh Healthcare Ltd

02920 485885 02920485885 00011875

damion.walters@arjo.com

paid

06/Jun/2024 Robert Connor

Repair SRN36491

Ref

S/N 1410000 PR02467A10

Equipment Type Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

1480000 Qty: 1 1430309 Qty: 1

V1000 has had transducer interface cushion replaced and calibration has been checked.