

Service Repair Sheet 68730

Contact Name	Stephen Glancy
Company/ Hospital Name	Queen Elizabeth University Hospital
Department	Medical Physics
Position	Specialist Clinical Technologist
Opera Account	00001853
Email	stephen.glancy@ggc.scot.nhs.uk
Order Number	GMPS13958745
Date Received	18/Mar/2024
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Calibrated
SRN36321	4410520	50840143	Capnograph	Time :0 Hour(s)

Parts Replaced

Qty: 1 4480520

The VM2500-S has been tested after being calibrated. The unit is working as expected.

Repair	Ref	S/N	Equipment Type	Calibrated
SRN36322	4410520	60940137	Capnograph	Time :0 Hour(s)

Parts Replaced

Qty: 1 4480520

The VM2500-S has been tested after being calibrated. The unit is working as expected.

Repair	Ref	S/N	Equipment Type	Calibrated
SRN36323	4410520	60940148	Capnograph	Time :0 Hour(s)

Parts Replaced

Qty: 1 4480520

The VM2500-S has been tested after being calibrated. The unit is working as expected.