

Service Repair Sheet SRS68789

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

C M Hor

Emstec Services

6046581791

00013104

cmhor@emstecmedical.com

28/May/2024

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 21/May/2024 Aqib Majeed

21/May/2024 Aqib Majeed

returning a faulty OOM113 sensor S/N: A100991 in the same box as the Foetal heart simulator (SRS68785)

28/May/2024 Robert Connor

Received 1 x OOM113 s/n A100990.

Ready For quote

Repair Complete Signed

C Green 11-6-24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36470	Oxygen Sensor	0110579	A100990	Yes

0140011

~~0140013~~ x 1 FOC

ETA S/N, SRS, SRN

~~0110879~~ x 1 FOC

New S/N, SRS

UPS - To ship with other repair