

Service Repair Sheet SRS68816

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Janice Hunter
Hunter and Co
Accounts

01383852049
01383852049
00020062
hunterandco@outlook.com

17/Jun/2024
Robert Connor
Viamed
Bring To Attention

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer
Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 17/Jun/2024 Robert Connor

17/Jun/2024 Robert Connor

Returned 1 x R22A s/n 958422, end-user claims barrier bag was open when sensor arrived.

17/Jun/2024 Robert Connor

Barrier bag appears to have been slashed open with a knife, this would not have been boxed this way as it is very obvious.

Ready For quote

Repair Complete Signed

CG Neen 28.6.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36494	Oxygen Sensor	0110122	958422	Yes

0140013 x 1 FOC
Old S/N, SRS, SRN

0110122 x 1 FOC
New S/N, SRS, SRN

UPS x 1 EO.