

Service Repair Sheet 68816

Contact Name	Janice Hunter
Company/ Hospital Name	Hunter and Co
Department	Accounts
Direct Phone	01383852049
General Phone	01383852049
Opera Account	00020062
Email	hunterandco@outlook.com
Date Received	17/Jun/2024
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN36494	0110122	958422	Oxygen Sensor	

Parts Replaced

Time :0 Hour(s)

Qty: 1 0110122

Replaced under warranty with S/N 136533
