

KG 01:00:00 PM For 4 Hours, MG Full, EC Full, EH Full



Martin James

CID29359 Opera CID29359 Type: **Vandagraph Retail**
Martin James 172 Telford Avenue , , Stevenage , Hertfordshire , SG2 0AT, United Kingdom
Tel **07305232728** GBP Retail Price List Vandagraph (0010) Log Call Add Issue
Proforma Credit Limit 0.00GBP

- Account Home
- Main Details
- Account Memos
- Sales History
- Stock References
- Cust./Supp. Returns
- Service Visits
- Distributor Agreements
- Documents Files
- Linked Issues
- Regulatory Agreements

SRS68818

SRS Created : 17 Jun 2024
Created By Ryan Swaine
Add Watch

- [Print Barcodes](#)
- [Print A4 Sheet](#)
- [Split Items into Different SRS Numbers](#)
- [Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload: No file chosen

Handle with care
Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Linked to Order Reference 151147

Service Repair Sheet 68818		Notes 17/Jun/2024 Ryan Swaine 17/Jun/2024 Ryan Swaine TEK-OX sn. TX 0463 Will not turn on, client has tried new batteries. Quote for repair Please pass to MG upon receipt. 25/Jun/2024 Robert Connor Received 1 x tek-ox s/n TX0463, with blue tee 26/Jun/2024 Catherine Spence Engineers room
Company / Hospital	Martin James	
Contact Name	Martin James	
Department		
Position		
Company Phone	07305232728	
Direct Phone	07305232728	
Opera Account	CID29359	
Email	martin.james1@ntlworld.com	
Order Number		
Viamed ORD Number		
Date Received Into building	25 Jun 2024	
Type	Quote Before Repair Move to Repair	
Issues?		

Items for Repair										
...										
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN36508	Oxygen Analyser TEK-OX	9710203 Requires Service Manual Linking in System	 311087	0463	Oxygen Analyser TEK-OX	No	No	Unfinished		00:00
SRN36508 Engineer Notes: INTERNAL NOTES not for customer discussion 03/Jul/2024 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. Corrosion has spread into the main compartment. The PCB powers up but gives a false reading. The battery and sensor contacts are corroded. The wiring harness would need to be replaced.										

Currently Viewing ITEM SRN36508 Oxygen Analyser TEK-OX 9710203 0463 Oxygen Analyser TEK-OX

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	03/Jul/2024 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. Corrosion has spread into the main compartment. The PCB powers up but gives a false reading. The battery and sensor contacts are corroded. The wiring harness would need to be replaced.	Non added Yet

ISO REVIEW

Please Select

Instructions