



Aqib Majeed <viamed.aqib.majeed@gmail.com>

Fwd: Capnograph device serial number: A1711160006 displays sensor fault

Main Account <office@viamed.co.uk>

23 July 2024 at 14:05

To: Aqib Majeed <aqib.majeed@vmsecure.me.uk>

----- Forwarded message -----

From: **Hussain Atif** <Atif.Hussain@bedsft.nhs.uk>

Date: Tue, 23 Jul 2024 at 14:01

Subject: Capnograph device serial number: A1711160006 displays sensor fault

To: orders@viamed.co.uk <orders@viamed.co.uk>Cc: office@viamed.co.uk <office@viamed.co.uk>, CLINICAL ENGINEERING (RC9) Luton & Dunstable Hospital TR <CLINICALENGINEERING@ldh.nhs.uk>

Good afternoon,

Capnograph device serial number: A1711160006 displays sensor fault, Please could you arrange repair for the device.

Kind regards

**Atif Hussain****Theatre Equipment Manager**

Clinical Engineering Department

Luton and Dunstable Hospital.

Bedfordshire Hospitals NHS Foundation Trust
Luton, LU4 0DZ**Direct Tel: 01582491166, Int Ext 2480****Visit:** www.bedsfordshirehospitals.nhs.uk

