

Service Repair Sheet SRS68841

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Terry Millen

University Hospital Crosshouse

Clinical Physics

Specialist Medical Physics Techn

01563826080

01563 521133

00001320

terry.millen2@aapct.scot.nhs.uk

15/Jul/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 09/Jul/2024 Steve Hardaker

09/Jul/2024 Steve Hardaker

Returning a VM-2500-S s/n 60920171 that is consistently alarming Sampling System Occlusion. After checking and changing the sample line several times, the fault is still occurring.

15/Jul/2024 Robert Connor

Received 1 x VM-2500-S s/n 60920171

Ready For quote

CANON 30.7.24

Repair Complete Signed _____

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36531	Capnograph	4410520	60920171	N

44400000 1/2 hr @ £90
S/N, SRN, SRS.

4480520 x 1 @ £150
SRS, SRN

4420504 x 1 @ £1,049.75
SRS, SRN

4430201 x 1 @ £15
SRS, SRN

UPS x 1 @ £12.