

To:  
VIAMED

Forth Valley  
Medical Physics Department  
Forth Valley Royal Hospital  
Stirling Road  
Larbert  
FK5 4WR



Date: Thursday, 01 August 2024

Tel: 01324-566-953  
Email: arlene.gallagher@nhs.scot

Dear Sir/Madam,

Please find enclosed the following item for repair/service/calibration.

Item: **V1000**

Equipment No.: **223735**

Serial No.: **PR02724A15**

Fault: **Annual calibration due**

If the work required is not covered under warranty or by a service contract please email a quote to the above address.

Please provide a service report when the item is returned.

Yours faithfully,

Arlene Gallagher