

Service Repair Sheet 68814

Contact Name

Company/ Hospital Name

Department

Position

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Paul Burrows

Nottingham University Hospital (Queens Medical Centre Campus)

Medical Equipment Services unit (MESU)

Clinical Engineering Technologist

01159249924

00003930

Paul.burrows@nuh.nhs.uk

200423134

19/Jun/2024

Robert Connor

Repair	Ref	S/N	Equipment Type
SRN36500	5610152	AL000100	Blender

Complete - Repaired
 Time :0 Hour(s)

Parts Replaced

Qty: 1 0380050

Qty: 1 0332004

Blender AL000100 has been stripped and ultrasonically cleaned. It has been rebuilt, using the service kit, and tested as per the service manual.