

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

rolays Bank PLC 78-42 20-78-124 90903124 GB45BUKB207842905 BUKBGB22 BUKBGB22 WW.vandagraph.com/

Service Repair Sheet 68853

Contact Name

Company/ Hospital Name

Direct Phone General Phone Opera Account

Email

Order Number Date Received Booked in By

Callum Baker

Chesterfield Royal Hospital

01246277271 01246277271 00001170

callum.baker@nhs.net

80097804 29/Jul/2024 Robert Connor

S/N SRN36560 1410000 PR0408A12 **Equipment Type** 

Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.