

Service Repair Sheet SRS68874

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Harry Webb

North Devon District Hospital

EBME Department

Medical Engineering Support Tech

01271322789

01271322577

00000290

harry.webb2@nhs.net

14/Aug/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 12/Aug/2024 Kate Griffiths

12/Aug/2024 Kate Griffiths

2 x MX300, one has physical damage around nO2 port and one not recognising new O2 probes. Will ask for serial numbers and cert of decontamination status

12/Aug/2024 Kate Griffiths

UPDATE, s/n 272873 given. They will just send ONE device in now. See pics

14/Aug/2024 Robert Connor

Received 1 x MX300 s/n 272873, 1 x 0131202 s/n 0014304, 1 x R-17MED s/n 917121, flow diverter, AX/MX stand with 2 suction cup feet. Sensor cable connector is pushed into the body of the device and the rear case panel is damaged.

Ready For quote

CCreen 20.8.24

Repair Complete Signed

CCreen 30.8.24

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|----------------------|-----------|---------------|----------|
| SRN37045 | Oxygen Monitor | 0111235 | 272873 | 2 |
| SRN37046 | Oxygen Monitor Cable | 0131202 | 0014304 | 2 |
| SRN37047 | Oxygen Sensor | 0110017 | 917121 | 2 |

0140005 x 0.75 @ £90 per hr
S/N, SRS, SRN

0131213 x 1 @ £70
SRS, SRN

0131214 x 1 £3.00
SRS, SRN

0131205 x 1 £6.00
SRS, SRN

Please Add. cg 30.8.24

0140025 x 1 FOC
S/N, SRS, SRN

0140011 x 1 FOC
S/N, SRS, SRN