

Service Repair Sheet 68866

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Aneta Szubarga

Euromed Medical Solution

0048618439059

603243071

00006582

a.szubarga@euromed.net.pl

paid proforma

13/Aug/2024

Robert Connor

Repair	Ref	S/N	Equipment Type
SRN37044	1410000	PR02968A11	Foetal Simulator

Complete - Repaired
Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
