



**Casco Antiguo
Comercial S.L.**

 **CID14659** Opera **CID14659** Type: **Vandagraph Trade**
Casco Antiguo Comercial S.L. Calle De Senda Galiana, C - No.16-18 , Coslada, Madrid, , 28821, Spain
Tel **0034 911510250** GBP Trade Price List Vandagraph (0009)
📞 Log Call ➕ Add Issue
Credit 30 Days after date of invoice Credit Limit 0.00GBP
VAT ESB79683579

- 🏠 Account Home 📝 Main Details 📄 Account Memos 📊 Sales History 📦 Stock References 🔄 Cust./Supp. Returns 🛠️ Service Visits 📄 Distributor Agreements
- 📁 Documents Files 🔗 Linked Issues 🔒 Regulatory Agreements

£10 Credit on Account 18/06/2024

New address from 01/07/24:
CASCO ANTIGUO COMERCIAL SL
CSEDA GALIANA C 16-18
28821 - COSLADA
MADRID

SRS68872

SRS Created : 08 Aug 2024
Created By Ryan Swaine
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care
Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68872		Notes
Company / Hospital	Casco Antiguo Comercial S.L.	08/Aug/2024 Ryan Swaine
Contact Name	Enrique Diaz Nunez	08/Aug/2024 Ryan Swaine
Department		VN202 sn. 03173, sold Nov 23. Not displaying anything other than 0.00, client has tried switching sensor and cable, but this did not resolve the issue.
Position	Technical Assistance Service	28/Aug/2024 Robert Connor
Company Phone	0034 911510250	Received 1 x VN202 s/n 03173, with 2 x AA battery, blue tee, metal adapter, coiled cable s/n 0002451, R-17VAN s/n 108660.
Direct Phone	+34 911510250	
Opera Account	CID14659	
Email	sat@cascoantiguo.com	
Order Number		

Viamed ORD Number	
Date Received Into building	28 Aug 2024
Type	Warranty
Issues?	

Items for Repair

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37068	Oxygen Analyser VN202	7910100 Requires Service Manual Linking in System	 1972428	03173	VN202mkII - Auto Switch Off	Yes	No	Unfinished		00:00

SRN37068 Engineer Notes: **INTERNAL NOTES not for customer discussion**
28/Aug/2024 Michael Green
The VN202mkII - Auto Switch Off has been tested. The unit appears to work as expected. A longer test will be performed.
28/Aug/2024 Michael Green
The supplied sensor cable has an intermittent fault.

SRN37069	Oxygen Sensor Vandagraph	0110217 Requires Service Manual Linking in System	 2286184	108660	Oxygen sensor R-17VAN	Yes	No	No Fault Found 28 Aug 2024 Michael Green	No Fault Found	00:00
--------------------------	--------------------------	---	---	--------	-----------------------	-----	----	--	----------------	-------

SRN37069 Engineer Notes: **INTERNAL NOTES not for customer discussion**
28/Aug/2024 Michael Green
The R-17VAN Oxygen sensor has been tested in air and Oxygen. No fault was found.

Currently Viewing ITEM SRN37068 Oxygen Sensor Vandagraph 0110217 108660 Oxygen sensor R-17VAN

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The R-17VAN Oxygen sensor has been tested in air and Oxygen. No fault was found.	28/Aug/2024 Michael Green The R-17VAN Oxygen sensor has been tested in air and Oxygen. No fault was found.	The R-17VAN Oxygen sensor has been tested in air and Oxygen. No fault was found.

ISO REVIEW

Please SelectInstructions