

SL Full



Andy Walters

CID29895 Opera CID29895 Type:
Andy Walters 32 Lyon Road, , Pontefract, , WF8 3PJ, United Kingdom
Tel **07725775778** GBP Retail Price List Vandagraph (0010)  Log Call

Add Issue

Proforma Credit Limit 0.00GBP

 Account Home

 Main Details

 Account Memos

 Sales History

 Stock References

 Cust./Supp. Returns

 Service Visits

 Distributor Agreements

 Documents Files

 Linked Issues

 Regulatory Agreements

SRS68867

SRS Created : 05 Aug 2024
Created By Ryan Swaine
Add Watch

- [Print Barcodes](#)
- [Print A4 Sheet](#)
- [Split Items into Different SRS Numbers](#)
- [Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload:

Choose file

No file chosen

Next

Handle with care

Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock

Unopened - will apply to all items on srs

☐ Clear From System - Force from System.

- will apply to all items on srs

Add notes to SRS

Add Notes

Service Repair Sheet 68867				Notes 05/Aug/2024 Ryan Swaine 05/Aug/2024 Ryan Swaine TEK-OX SN. TX3583, around 18 months old, belongs to club. Sometimes it is difficult to turn on. 08/Aug/2024 Robert Connor Received 1 x tek-ox s/n TX3583, with blue tee and hard yellow case. 27/Aug/2024 Catherine Spence Engineers Room LINKED ISSUE NOTES: 339401: AutoGenerated Issue SRS68867 Appears to be Complete 30 Aug 2024 Catherine Spence Noted. Vandagraph repair						
Company / Hospital	Andy Walters									
Contact Name	Andy Walters									
Department										
Position										
Company Phone	07725775778									
Direct Phone	07725775778									
Opera Account	CID29895									
Email	andywaltersuk@icloud.com									
Order Number										
Viamed ORD Number										
Date Received Into building	08 Aug 2024									
Type	Warranty									
Issues?	339401									

Items for Repair										
...										
SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)

SRN37043	Vandagraph Tek Ox	7910201 Requires Service Manual Linking in System	 1848309	TX3583	Oxygen Analyser Tek-Ox + Quick-Ox	Yes	No	Complete - Repaired 28 Aug 2024 Michael Green	Intermittent power	00:15
SRN37043 Engineer Notes: INTERNAL NOTES not for customer discussion 28/Aug/2024 Michael Green The Tek-Ox analyser has been tested. An intermittent power connection fault is causing the unit to shut down. 28/Aug/2024 Michael Green The Tek-Ox analyser has been repaired. The battery contacts have been cleaned.										

Currently Viewing ITEM SRN37043 Vandagraph Tek Ox 7910201 TX3583 Oxygen Analyser Tek-Ox + Quick-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. The battery contacts have been cleaned.	28/Aug/2024 Michael Green The Tek-Ox analyser has been tested. An intermittent power connection fault is causing the unit to shut down. 28/Aug/2024 Michael Green The Tek-Ox analyser has been repaired. The battery contacts have been cleaned.	The Tek-Ox analyser has been repaired. The battery contacts have been cleaned.

[-](#)

ISO REVIEW

Please Select

Instructions