

Service Repair Sheet 68879

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Clay Harper

Sage Services Group

8432845844

8772817243

00006261

harper@sageservicesgroup.com

28/Aug/2024

Robert Connor

---

Repair	Ref	S/N	Equipment Type
SRN37066	1410000	PR01883A18	Foetal Simulator

Complete - Repaired  
Time :0 Hour(s)

Parts Replaced

Qty: 1 1480000

Qty: 1 1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

---