

Service Repair Sheet SRS68877

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Muhammad Sami Uddin Naseer
Ergea UK and Ireland Limited

Field Service Engineer (East)
0118 900 8140

00013122
sami.naseer@ergeagroup.com

21/Aug/2024
Robert Connor
Viamed
Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 15/Aug/2024 Sophie Lines

15/Aug/2024 Sophie Lines

Sending Microstim DB3 for repair - serial number M0004677. Email from Sami Nadeer attached.

21/Aug/2024 Robert Connor

Received 1 x DB3 s/n M0004677, with 9v battery and patient lead.

Ready For quote

CGreen 29.8.24

Repair Complete Signed

CGreen 9.9.24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37065	Microstim DB3	2510000	M0004677	N

2540010 x 1 £60

S/N, SRS, SRN

UPS x 1 @ £12