

Vidilled Lilling to oldion Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68887

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone General Phone

Opera Account

Email

Order Number **Date Received** Booked in By

Claire Willis

Medway Maritime Hospital

Clinical Engineering

Clinical Engineering Inventory and Systems Assistant

01634976451 01634830000

00001770

c.willis2@nhs.net

250008001 11/Sep/2024 Robert Connor

Repair

Ref

S/N

SRN37079 1410000 PR0773A31

Equipment Type

Foetal Simulator

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

Qty: 1

1480000

Qty: 1

1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.