

Le comment Linean CLOSS LINE Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68880

Contact Name

Company/ Hospital Name

Department Position Direct Phone General Phone

Opera Account

Email

Order Number Date Received Booked in By

David Watson

Darlington Memorial Hospital Clinical Engineering Department Clinical Engineering Technician

01325743048 01325380100 00001350

david.watson28@nhs.net

CDD0006116445 28/Aug/2024 Robert Connor

Repair SRN37067 0310030 VMBC18

Ref

S/N

Equipment Type Tom Thumb

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

0380000 Qty: 1

Tom Thumb TT480 VMBC18 has been stripped and cleaned then reassembled with new O rings. The two valves have been checked and reset before QA.