

Sent back to
• requested RMA
eg 20.8.24

Service Repair Sheet SRS68855

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Atif Hussain

Luton & Dunstable Hospital

Clinical Engineering Department

Theatre Equipment Manager

01582491166 ext 2480

01582497042

00003490

atif.hussain@ldh.nhs.uk

SRS68855

29/Jul/2024

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☐

Cleaned by Viamed,
if no declaration certificate
from customer ☐

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 23/Jul/2024 Aqib Majeed

23/Jul/2024 Aqib Majeed

customer has a Capnograph Device which displays sensor fault, SN number is A17111600006, no warranty on device.

29/Jul/2024 Robert Connor

Received 1 x VM-2500-S s/n A1711160006, with silicone cover.

Ready For quote

Cgreen 13-9-24

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN36564	Capnograph	4410520	A1711160006	N

4440000 x 1 1/2 hr @ £90 per hour

S/N, SRS, SRN

4480520 x 1 @ £150
SRS, SRN

4420504 x 1 @ £1,049.75
SRS, SRN

4430201 x 1 @ £15
SRS, SRN

UPS x 1 £12.