



Viamed Limited - 15 Station Road - Cross Hills
Keighley - West Yorkshire - BD20 7DT - United Kingdom
Tel: +44 (0)1535 634 542 - Fax: +44 (0)1535 635 582
Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68894

Contact Name

Company/ Hospital Name

Position

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Abbey McAnaney

Vet Direct Services Ltd

Technical Support RVN

01912642705

01912642705

00012824

tech@vet-direct.com

09/Sep/2024

Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37074	0111275	A106106	Oxygen Analyser	Complete - Repaired
Parts Replaced				Time :0 Hour(s)

Qty: 1 0131880

The device was reading around 90% minimum in air and the On/Off button was cracked.

I have performed a reset to get the device back to 20.9% and replaced the display membrane under warranty.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37075	0110660	A110805	Oxygen Sensor	No Fault Found
				Time :0 Hour(s)