

Viamed Limited - 15 Station Road - Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68891

Contact Name

Company/ Hospital Name

Department Position

General Phone Opera Account

Email

Order Number Date Received Booked in By

Paul Burrows

Nottingham University Hospital ( Queens Medical Centre Campus)

Medical Equipment Services unit (MESU)

Clinical Engineering Technologist

01159249924 00003930

Paul.burrows@nuh.nhs.uk

202002942 09/Sep/2024 Robert Connor

Repair

Ref

S/N

SRN37076 5610152 AL000091

Equipment Type Blender

Complete - Repaired Time: 0 Hour(s)

Parts Replaced

0332004 Qty: 1 Qty: 1 0380050

Blender AL000091 has been stripped and ultrasonically cleaned. It has been rebuilt, using the service kit, and tested as per the service manual.