

Repair Quotation Request

Date of request: 20/09/2024



Oxford University Hospitals
NHS Foundation Trust

Post to:

Returns Dept - SRS68904
Viamed Ltd.
15 Station Road
Cross Hills
Keighley
BD20 7DT

Deliver To:

Clinical Engineering
Industrial Block
John Radcliffe Hospital
Headley Way
OX3 9DU

Telephone: 01865 221548

Email: Clinical.engineering@ouh.nhs.uk

The following item(s) of equipment are reported faulty and require testing/repair.

Brand: VIAMED
Model: MICROSTIM DB3
Serial No: M0005194
Asset No: 102911

The reported fault:

No signal output – new batteries tried.

Please carry-out an evaluation and forward a quotation to Clinical Engineering at the following address: Clinical.engineering@ouh.nhs.uk

Please include the **Job reference 653195** in all quotes and correspondence related to this request.

Kind regards,

Clinical Engineering