Service Repair Sheet SRS68883

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone

Opera Account

Email

Order Number Date Received Booked in By

Main Company

Type Return

D.Gunasinghe

Eastbourne District General Hospi

Clinical Engineering

01323417400 01323417400 00004832

d.gunasinghe@nhs.net

04/Sep/2024 Robert Connor

Viamed Quote

VIAMEDclean Goods In Only Decontamination certificate provided V by customer Cleaned by Viamed, Signed: Date: .

Goods Out Only

Cleaned by Viamed before returning to customer Signed:

Date:

Notes 23/Aug/2024 Kate Griffiths 23/Aug/2024 Kate Griffiths

DB3 does not switch on. They have changed the battery. S/N: M0004873. Asked for cert of decontamination 04/Sep/2024 Robert Connor

Received 1 x DB3 s/n M0004873, with patient lead and hard plastic carry case.

Ready For quote

CGNOON 16.9.24

Repair Complete Signed

CGreen 2-10-24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37072	Microstim DB3	2510000	M0004873	2

2540010 × 1 2 60 SIN, SRS, SEN UPS × 1 2 EIZ.