

Service Repair Sheet SRS68895

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sudath Weeraman

Prime Lanka Associate

9410718732285

00006714

sudathweeraman17@gmail.com

02/Oct/2024

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 11/Sep/2024 Kate Griffiths

11/Sep/2024 Kate Griffiths

Sudath will return 1 x MAX-250E, s/n JL55299057 - ``defective``

11/Sep/2024 Kate Griffiths

Update: Sudath says the fault is ``sensor error during calib. process``

02/Oct/2024 Robert Connor

Received 1 x MAX-250E s/n JL55299057

Ready For quote

Repair Complete Signed

CGREEN 3-10-24

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37116	Oxygen Sensor	0110429	JL55299057	Yes

0140013 x 1 fOC
old S/N, SRS, S/N

0110429 x 1 fOC
new S/N, SRS, S/N

EXW. (ask customer if shipping now or with next order)
Placed. cg 3-10-24