

Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634 542 · Fax: +44 (0)1535 635 582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Time: 0 Hour(s)

Service Repair Sheet 68895

Contact Name

Company/ Hospital Name

Direct Phone Opera Account

Email

Date Received Booked in By Sudath Weeraman Prime Lanka Associate

9410718732285 00006714

sudathweeraman17@gmail.com

02/Oct/2024 Robert Connor

Repair Ref S/N SRN37116 0110429 JL55299057 Equipment Type Oxygen Sensor

Under Warranty

Parts Replaced

Qty: 1 0110429

Replaced under warranty with S/N KG85699081